

PUBLIC SURVEY  
FIELD NOTES

VOL. 511

4916 - 4922

1934 - 1939

PUBLIC SURVEY

FIELD NOTES

VOL. 511

4916 - 4922

1934-1939

4-679  
(April 1933)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GENERAL LAND OFFICE

54

BOOK "O"

## FIELD NOTES

4917

OF THE

DEPENDENT RESURVEY

OF THE

SOUTH AND WEST BOUNDARIES

AND OF THE

SUBDIVISIONS

OF

TOWNSHIP 15 NORTH, RANGE 95 WEST

Of the 6 TH PRINCIPAL Meridian,

In the State of WYOMING

EXECUTED BY

MARVIN J. LYITLE, CADASTRAL ENGINEER

ROSS W. MOOR, TRANSITMAN

ELMER C. LENHART, PUBLIC LAND SURVEYOR

Under special instructions dated MARCH 21, 1934, which provided for the surveys included under Group No. 133, bearing the approval of the Commissioner of the General Land Office under date of APRIL 18, 1936 and assignment instructions dated 5/22/34, 5/6/36, 19 4/11/38

Survey commenced AUGUST 21, 1934

Survey completed OCTOBER 22, 1938

# INDEX DIAGRAM.

*Township* 15 NORTH, *Range* 95 WEST

13 47	6 47	48 47	5 39	39 39	4 33	3 33	27 26	2 26	20 20
12 46	7 46	46 45	8 38	9 10	32 31	10 31	26 25	11 25	19 18
11 44	18 44	45 44	17 36	16 36	37 30	15 30	24 24	14 24	18 17
10 42	19 42	43 42	20 35	21 29	36 29	21 28	23 23	23 23	24 16
10 41	30 41	41 40	29 34	28 34	28 28	27 28	22 22	26 22	25 15
9 7	31 6	40 6	32 5	33 5	27 4	34 4	21 4	35 3	36 3

6-151

- Lines retraced by Ross W. Moor, Transitman
- - - Lines retraced by Marvin J. Lytle, Cadastral Engineer
- Lines resurveyed by Marvin J. Lytle, Cadastral Engineer
- Lines retraced and resurveyed by Elmer C. Lenhart

## Dependent Resurvey, T. 15 N., R. 95 W.

The resurvey of the subdivisional lines of the township was commenced on September 23, 1938 and completed on October 22, 1938, by Elmer C. Lenhart, Public Land Surveyor, using Gurley Transit No. 2349. The instrument is the property of the General Land Office, and conforms to the standard instrumental requirements of the Cadastral Engineering Service. It is equipped with a full vertical circle and improved Smith type Solar Attachment.

All the subdivisional lines are back and foresight transit lines, double centered when necessary. The subdivisional lines are carried by deflection from the south boundary, checked by deflection against the other boundaries, and further satisfactorily verified by altitude observations upon the sun for meridian.

Frequent tests of the transit are made during the progress of the resurvey and it is at all times in good adjustment.

Measurements are made with Lallie steel tapes, 5 chains in length, tested for accuracy by comparison with a Lufkin 66-ft. steel standard tape reserved for that purpose. Measurements are made on the slope, the vertical angles determined by clinometers in good adjustment and the slope measurements reduced to true horizontal distances which alone appear in the field note record.

Preliminary to the resurvey, the lines of the original survey are retraced and diligent search is made for all original corners. Identified corners of the original survey are re-monumented in their original positions. All lost corners are reestablished at proportionate positions, based on the record of the original survey. The retrace data are thoroughly verified and for the sake of simplicity, only the true line notes are given herein.

3

Dependent Resurvey of the South Boundary of T.s 15 N., R. 95 W.

**Chains.**

Reestablishment of the survey executed by Edw. F. Stahle,  
U.S. Deputy Surveyor, in 1882.

This boundary was retraced by Ross W. Moor, Transitman,  
on August 21 and 23, 1934, using Young and Sons solar  
transit No. 8518, description and test of which is  
given in the record of the resurvey of T. 15 N., R. 93 W.

The resurvey was made by Marvin J. Lytle, U.S. Cadastral  
Engineer, on June 9, 1936, with Buff solar transit  
No. 9219. For description and test of this instrument  
and the method of obtaining data upon which the resurvey  
is based, see the record of the resurvey of the West  
Boundary of T. 13 N., R. 95 W.

From the cor. of Ts. 14 and 15 N., Rs. 94 and 95 W., a  
3-inch iron post, described in the field notes of the  
resurvey of the South Boundary of T. 15 N., R. 94 W.

N.  $89^{\circ} 55'$  W., on true line, bet. secs. 1 and 36.

Over rolling semi desert, with general SW. slope, through  
sagebrush.

- 3.25 Dry wash, course S.  $30^{\circ}$  W.
- 8.60 Dry wash, course S.  $70^{\circ}$  W.
- 19.00 Dry wash, course S.  $70^{\circ}$  W.
- 25.30 Head of dry wash, course S.  $70^{\circ}$  W.
- 39.91 At proportionate point.
- Set an iron post, 3 ft. long, 1 in. diam., 18 ins. in the  
ground to solid rock, and supported by a mound of stone  
18 ins. high, for the restored  $\frac{1}{2}$  sec. cor., with brass  
cap marked  
S 36  
 $\frac{1}{2}$  —  
S 1  
1936
- 61.20 Dry wash, course S.  $30^{\circ}$  W.
- 66.70 Dry wash, course south for 5 chains to junction with main  
wash.
- 77.80 Top of adobe spur, projects S.  $20^{\circ}$  W. for 10 chains.
- 79.83 At proportionate point

Set an iron post, 3 ft. long, 2 ins. diam., 10 ins. in the  
ground, to solid rock and enclosed to top in mound of  
stone, for the restored cor. of secs. 1, 2, 35 and 36,  
with brass cap marked

T15N	R95W
S 35	S 36

S 2	S 35
T14N	
1936	

This corner falls on steep W. slope of spur.

## Dependent Resurvey of the South Boundary of T. 15 N., R. 95 W.

	<b>Chains.</b>	
		Land, rolling semi desert with general SW. slope. Soil, 3rd and 4th rate, adobe, rocky and sand. Vegetation, sparse sagebrush. Timber, none.
		N. 89° 55' W., on true line, bet. secs. 2 and 35.
		Over rolling semi desert in wide bad land valley, through sagebrush..
12.50		Top of small adobe butte.
23.00		East bank of wide, shallow dry wash, course S. 30° E.
31.30		West bank of wash; thence over bottom land through dense sagebrush.
39.91½		At proportionate point. Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored ¼ sec. cor., with brass cap marked
		S 35 — S 2 1936
		raise a mound of stone, 2½ ft. base, 1½ ft. high, N. of post.
45.00		Leave bottom land and dense sagebrush and enter very broken adobe bad lands, edge bears generally NW. and SE.; ascend.
53.80		Dry wash, course N. 70° E.
62.40		Dry wash, course N. 85° E.
64.10		Dry wash, course south for 2 chains, thence N. 85° E.
79.83		At proportionate point Set an iron post, 3 ft. long, 2 ins. diam., 6 ins. in the ground, to solid rock and supported by a mound of stone 30 ins. high, for the restored cor. of secs. 2, 3, 34 and 35, with brass cap marked
		T15N   R95W S 34   S 35 — S 3   S 2 T14N 1936
		Land, rolling semi desert valley floor and very broken adobe bad lands. Soil, 3rd rate and 4th rate adobe, rocky and sand. Vegetation, sagebrush and greasewood. Timber, none.
		N. 89° 55' W., on true line, bet. secs. 3 and 34.
		Through very broken adobe bad lands, general N. 70° E. slope.
0.50		Dry wash, course N. 85° E.
18.10		Dry wash, course N. 30° E.

Dependent Resurvey of the South Boundary of T. 15 N., R. 95 W.

Chains.

25.40 Dry wash, course N.  $60^{\circ}$  E. 00.00

39.91 $\frac{1}{2}$  At proportionate point. 00.00

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored  $\frac{1}{4}$  sec. cor., with brass cap marked

S 34

$\frac{1}{4}$  —

S 3

1936

raise a mound of stone, 2 $\frac{1}{2}$  ft. base, 1 $\frac{1}{2}$  ft. high, N. of post.

47.50 Dry wash, course N.  $70^{\circ}$  E. 00.00

52.10 Top of small butte. 00.00

59.10 Dry drain, course N.  $60^{\circ}$  E. 00.00

76.60 Dry wash, course NE. 00.00

79.83 At proportionate point

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for the restored cor. of secs. 3, 4, 33 and 34, with brass cap marked

T15N | R95W

S 33 | S 34

— —

S 4 | S 3

T14N

1936

raise a mound of stone, 2 $\frac{1}{2}$  ft. base; 1 $\frac{1}{2}$  ft. high, W. of post.

Land, broken adobe bad lands, general N.  $70^{\circ}$  E. slope.

Soil, 3rd and 4th rate adobe, and rocky.

Vegetation, sparse sagebrush and greasewood.

No timber.

N.  $89^{\circ} 55'$  W., on true line, bet. secs. 4 and 33.

Ascend broken N.  $70^{\circ}$  E. slope through adobe bad lands.

4.90 Dry wash, course N.  $30^{\circ}$  E. 00.00

12.10 Head of dry drain, course NE. 00.00

13.30 Top of ascent and irregular rim of adobe escarpment, bears NW. and S.  $30^{\circ}$  E., faces NE.; descend gentle W. slope of cuesta which extends NW. approximately 9 miles.

39.91 $\frac{1}{2}$  At proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored  $\frac{1}{4}$  sec. cor., with brass cap marked

S 33

$\frac{1}{4}$  —

S 4

1936

raise a mound of stone, 2 ft. base, 1 $\frac{1}{2}$  ft. high, N. of post.

## Dependent Resurvey of the South Boundary of T. 15 N., R. 95 W.

Chains.

- 66.60 Dry drain, course NW.  
79.83 At proportionate point  
Set an iron post, 3 ft. long, .2 ins. diam., 27 ins. in  
the ground, for the restored cor. of secs. 4, 5, 32 and  
33, with brass cap marked

T15N	R95W
S 32	S 33
<hr/>	
S 5	S 4

T14N

1936

raise a mound  
of stone, 2½ ft. base, 1½ ft. high, W. of post.

Land, east 13.30 chains broken adobe bad lands; west  
66.50 chains rolling plain sloping gently west.

Soil, 3rd and 4th rate adobe rocky and sand.  
Vegetation, sagebrush and greasewood.  
Timber, none.

N. 89° 55' W., on true line, bet. secs. 5 and 32.

Descend gentle W. slope of slightly rolling plain, small,  
low sand dunes, scattered sagebrush.

19.50 Dry wash, course N. 20° W.; continue descent.

26.60 Dry wash, course N. 20° W.; continue descent.

39.91 At proportionate point

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the  
ground, for the restored ¼ sec. cor., with brass cap  
marked

S 32

S 5

1936

Continue descent of nearly uniform 1° W. slope.

79.83 At proportionate point

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in  
the ground, for the restored cor. of secs. 5, 6, 31 and  
32, with brass cap marked

T15N

R95W

S 31

S 32

---

S 6

S 5

T14N

1936

raise a mound  
of stone, 2½ ft. base, 1½ ft. high, W. of post.

Land, gently rolling, approximate 1° W. slope.

Soil, 3rd rate clay and sand.

Vegetation, sagebrush.

Timber, none.

Dependent Resurvey of the South Boundary of T. 15 N., R. 95 W.

Chains.	N. 89° 55' W., on true line, bet. secs. 6 and 31. Descend gentle W. slope, approximately 1°, through small, low sand dunes and sagebrush.
18.80	Small dry wash, course S. 70° W. to junction with main dry wash, 2 chains distant.
21.20	Main dry wash, course N. 30° W.
39.91½	At proportionate point  Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored $\frac{1}{4}$ sec. cor., with brass cap marked
	S 31 $\frac{1}{4}$ — S 6 1936
	raise a mound of stone, $2\frac{1}{2}$ ft. base, $1\frac{1}{2}$ ft. high, N. of post.
78.17	The cor. of Ts. 14 and 15 N., Rs. 95 and 96 W., a 3-inch iron post set, marked and witnessed as described in the field notes of the resurvey of the E. Bdy. of T. 14 N., R. 96 W.  Land, gently rolling 1° W. slope. Soil, 3rd rate clay and sand. Vegetation, scattered sagebrush. Timber, none.

## Dependent Resurvey of the West Boundary of T. 15 N., R. 95 W.

Chains. Reestablishment of the survey executed by Edw. F. Stahle,  
U.S. Deputy Surveyor, in 1882.

The north four miles of this boundary, were retraced by Ross W. Moor, Transitman, on August 31, 1934, using Young and Sons solar transit No. 8518, for description and test of which see field notes of the resurvey of T. 15 N., R. 95 W.

The south two miles were retraced on May 18, 1936, and the resurvey made on June 3, 1936, by Marvin J. Lytle, U.S. Cadastrel Engineer, using Buff solar transit No. 9219. For description and test of the instrument and for the method of obtaining data upon which the resurvey is based, see record of the resurvey of the W. bdy. of T. 15 N., R. 95 W.

From the cor. of Tps. 14 and 15 N., Rs. 95 and 96 W., which is an iron post, 3 ins. diam., properly set, marked and witnessed as described in the field notes of the resurvey of the **East** Boundary of T. 14 N., R. 96 W.

N.  $0^{\circ} 17'$  E., on true line, bet. secs. 31 and 36.

Ascend very gradually over gently rolling W. slope, changing to SW., through scattered sagebrush and greasewood.

41.80 Dry wash, course S.  $65^{\circ}$  W.

34.00 Top of small sand dune.

40.11 At proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored  $\frac{1}{4}$  sec. cor., with brass cap mkd.

S36 | S31  
1936

raise a mound of stone, 2 ft. base, 1 $\frac{1}{2}$  ft. high, W. of post.

41.80 Top of small sand dune.

50.20 Dry wash, course SW.

80.22 At proportionate point.

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in ground, for the restored cor. of secs. 25, 30, 31 and 36, with brass cap mkd.

T15N  
R96W | R95W  
S25 | S30  
S36 | S31  
1936

raise a mound of stone, 3 ft. base, 2 ft. high, W. of post.

Land, rolling.

Soil, 3 rd rate clay and sand, with some gravel.

Vegetation, scattered sagebrush and greasewood.

Timber, none.

## Dependent Resurvey of the West Boundary of T. 15 N., R. 95 W.

	Chains.	N. 0° 17' E., on true line, bet. secs. 25 and 30. Over rolling land, ascend slightly, through sparse sagebrush and greasewood.
5.00		Top of low, broad spur, slopes W.; thence along very gradual W. slope.
20.90		Shallow, dry wash, course NW.
39.00		Top of low, elongated sand dune, bears N. 60° W., and S. 60° E.
40.11		At proportionate point. Set an iron post, 3 ft. long; 1 in. diam., 27 ins. in the ground, for the restored 1 sec. cor., with brass cap mkd.
		S25   S30 1936
		raise a mound of stone, 2 ft. base, 1½ ft. high, W. of post.
64.00		Top of small, low sand dune.
65.20		Dim, ungraded road, bears N. 50° E., and S. 70° W.
78.90		Dry wash, course S. 30° W.
80.22		At proportionate point. Set an iron post, 3 ft. long, 2 ins. diem., 27 ins. in the ground, for the restored cor. of secs. 19, 24, 25 and 30, with brass cap mkd.
		T15N R95W   R95W S24   S19 S25   S30 1936
		raise a mound of stone, 2 ft. base, 1½ ft. high, W. of post.
		Land, rolling, general W. slope. Soil, 3 rd rate clay and loose sand. Vegetation, sparse sagebrush and greasewood. Timber, none
		N. 0° 17' E., on true line, bet. secs. 19 and 24.
		Along course of main dry wash, through sparse sagebrush and greasewood.
35.60		Main dry wash, course winding S., from N. 10° E.
40.11		At proportionate point. Set an iron post, 3 ft. long, 1 in. diam., 24 ins. in the ground to hard shale, and supported by a mound of stone 12 ins. high, for the restored 1 sec. cor., with brass cap mkd.

## Dependent Resurvey of the West Boundary of T. 15 N., R. 95 W.

Chains.

	1
S24	S19
1936	

raise a mound of stone, 2 ft. base, 1 $\frac{1}{2}$  ft. high W. of post.

58.10 Dry wash, course E. to main wash, 3 chs. dist.

80.22 At proportionate point.

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in ground, for the restored cor. of secs. 13, 18, 19 and 24, with brass cap mkd.

T15N	
R96W	R95W
S13	S18
S24	S19
1936	

raise a mound of stone, 2 $\frac{1}{2}$  ft. base, 1 $\frac{1}{2}$  ft. high, W. of post.

Land, rolling semi desert.

Soil, 3rd rate, clay, shale and loose sand.

Vegetation, sparse sagebrush and greasewood.

Timber, none.

N. 0° 17' E., on true line, bet. secs. 13 and 18.

1.00 Enter broken bed lands, edge bears gener lly N. 30° E. and S. 30° W.

16.30 Top of broken ascent and irregular edge of escarpment, bears N. 30° E., and S. 30° W., thence through very broken bed lands, with general W. slope.

18.60 Bottom of dry ravine, course W.

40.11 At proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 12 ins. in the ground to solid rock and supported by a mound of stone 24 ins. high, for the restored 1 sec. cor., with brass cap mkd.

	1
S13	S18
1936	

41.00 Dry wash, course S. 80° W., and heading at a gap in escarpment approximately 20 chains to E.

51.00 Dry wash, course S. 70° W.

56.70 Enter rolling mesa, edge bears NE. and SW.; thence along gentle W. slope.

68.20 Leave mesa, edge bears E. and W.; enter broken bed lands.

80.22 At proportionate point.

## Dependent Resurvey of the West Boundary of T. 15 N., R. 95 W.

Chains.	Set an iron post, 3 ft. long, 2 ins. diam., 8 ins. in the ground to solid rock and supported by a mound of stone 28 ins. high, for the restored cor. of secs. 7, 12, 13 and 18, with brass cap mkd.	T15N R96W   R95W S12   S7 ----- S13   S18 1936
		Lend, broken bad lands, except for narrow mess noted above. Soil, 3rd and 4th rate, adobe and rocky. Vegetation, sparse sagebrush, salt sage and greasewood. Timber, none.
		N. 0° 17' E., on true line, bet. secs. 7 and 12.
		Through broken bad lands, general W. slope.
9.20	Bottom of main dry ravine, course W.	
17.40	Short spur, slopes W.	
25.30	Short sharp spur, slopes W.; general slope changes to NW.	
27.60	Dry wash, course W.	
28.50	Leave broken bad lands, edge bears irregularly E. and W.; thence over rolling semi desert with gentle NW slope, through small and low sand dunes.	
40.11	At proportionate point	
	Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored cor. of sec. 1, with brass cap marked.	S12   S7 ----- 1936
	raise a mound of stone, 21 ft. base, 1½ ft. high, W. of post.	
41.30	Small dry wash, course W. from S. 60° E.	
69.80	Dim, ungraded road, bears N. 70° E. and S. 60° W.; slope changes to gentle W.	
80.22	At proportionate point.	
	Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for the restored cor. of secs. 1, 6, 7 and 12, with brass cap mkd.	T15N R96W   R95W S1   S6 ----- S12   S7 1936
	no stone or memorial material available, pits impracticable.	

## Dependent Resurvey of the West Boundary of T. 15 N., R. 95 W.

65

Chains.

Land, broken bad lands, S. 28.50 chs.; rolling semi desert N. 51.50 chs.  
 Soil, 3rd and 4th rate hard adobe, rocky and loose sand.  
 Vegetation, sparse sagebrush and greasewood.  
 Timber, none.

N. 0° 17' E., on true line, bet. secs. 1 and 6.

Over rolling semi desert with gentle W. slope.

9.00

Dry wash, course W.

40.11

At proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored 1 sec. cor., with brass cap mkd.

	1
S1	S6
1936	

no stone or  
memorial material available, pits impracticable.

42.90

Dry wash, course S. 70° W.

61.90

Dry wash, course SW.

80.22

At proportionate point.

Set an iron post, 3 ft. long, 3 ins. diam., 27 ins. in the ground, for the restored cor. of Tps. 15 and 16 N., Rs. 95 and 96 W., with brass cap mkd.

T16N	
R96W	R95W
S36	S31
<hr/>	
S1	S6
T15N	
1936	

raise a mound  
of stone, 2½ ft. base, 1½ ft. high, S. of post.

Land, rolling semi desert with gentle W. slope.  
 Soil, 3rd rate, adobe and loose sand.  
 Vegetation, scattered sagebrush and greasewood.  
 Timber, none.



## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.

Reestablishment of the survey executed by Edward F. Stahle, ~~H.S.~~, Deputy Surveyor, in 1882.

From the cor. of secs. 1, 2, 35 and 36, on the S. bdy. of the Tp., hereinbefore described.

N.  $0^{\circ} 18' E.$ , on true line, bet. secs. 35 and 36.

Over rolling desert, through sagebrush and greasewood.

8.74 Low spur, slopes SW.

15.75 Low spur, slopes SW.

40.11 At proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 12 ins. in ground to underlying rock and in a mound of stone to top, for the restored 1 sec. cor., with brass cap mkd.

S35 | S36

1938

.72.78 Dry wash, course generally W.; drains into Sand Creek.

80.22 At proportionate point.

Set an iron post, 3 ft. long, 2 ins. diam., 12 ins. in ground and in a mound of stone to top, for the restored cor. of secs. 25, 26, 35 and 36, with brass cap mkd.

T15N R95W  
S26 | S25  
S35 | S36  
1938

Land, rolling desert.

Soil, sandy clay and rocky; 2d and 3d rate.

Vegetation, sagebrush and greasewood.

Timber, none.

From the cor. of secs. 25, 30, 31 and 36 on the E. bdy. of the Tp., which is an iron post, 2 ins. diam., properly set, marked and witnessed as described in the field notes of the resurvey of the West Boundary of T. 15 N., R. 94 W.

S.  $90^{\circ} 56' W.$ , on true line, bet. secs. 25 and 36.

Over rolling desert, through sparse sagebrush.

17.95 Dry drain, course SW.

22.58 Spur, slopes SW.

24.88 Dry drain, course generally S.

36.95 Dry drain, course generally S.

39.89 At proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 18 ins. in

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.	the ground, for the restored 1/2 sec. cor., with brass cap mkd.
	<u>1 S25</u> S26 1938
39.99	Small dry wash, course S. 40° E. . .
79.78	The cor. of secs. 25, 26, 35 and 36.  Land, rolling desert. Soil, 2d and 3d rate; sandy clay and rocky. Vegetation, sagebrush. Timber, none.
4.98	N. 0° 03' W., on true line, bet. secs. 25 and 26
40.11	Over rolling to broken desert, through sparse sagebrush.  Dry wash, course S. 60° W. At proportionate point. Set an iron post, 3 ft. long, 1 in. diam., 6 ins. in ground to underlying rock and in a mound of stone to top, for the restored 1/2 sec. cor., with brass cap mkd.
	\$ S26 S25✓ 1938
42.28	Dry Wash, course generally W.
80.22	At proportionate point.  Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for the restored cor. of secs. 23, 24, 25 and 26, with brass cap mkd.
	T15N R95W S23 S24 S26 S25 1938
	raise a mound of stone, 2 1/2 ft. base, 2 1/2 ft. high, W. of post.
	Land, rolling to broken desert. Soil, sandy clay and rocky; 3d rate. Vegetation, sparse sagebrush. Timber, none..
40.08	From the cor. of secs. 10, 24, 25 and 30, on the E. bdy. of the Tp., which is an iron post, 2 ins. diam., properly set, marked and witnessed as described in the field notes of the resurvey of the W. Bdy. of T. 15 N., R. 94 W.  S. 89° 55' W., on true line, bet. secs. 24 and 25.  Over rolling to broken desert, through sparse sagebrush.  At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 4 ins. in ground to underlying rock and in a mound of stone to

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains. top, for the restored  $\frac{1}{4}$  sec, cor., with brass cap mkd.

$\frac{1}{4}$  S24  
S25  
1938

74.76 Small dry wash, course N.

80.16 The cor. of secs. 23, 24, 25 and 26.

Land, rolling and broken desert.  
Soil, sandy clay and rocky; 3d rate.  
Vegetation, sparse sagebrush.  
Timber, none.

N.  $0^{\circ} 13'$  E., on true line, bet. secs. 23 and 24.

Over rolling and broken desert, through sparse sagebrush.

2.36 Dry wash, course SW.

40.11 At proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 6 ins. in ground to underlying rock and in a mound of stone to top, for the restored  $\frac{1}{4}$  sec. cor., with brass cap mkd.

$\frac{1}{4}$   
S23|S24  
1938

80.22 At proportionate point.

Set an iron post, 3 ft. long, 2 ins. diam., 16 ins. in the ground to underlying rock and in a mound of stone to top, for the restored cor. of secs. 13, 14, 23 and 24, with brass cap mkd.

T15N R95W  
S14|S13  
S23|S24  
1938

Land, rolling and broken desert.  
Soil, sandy clay and rocky; 3d rate.  
Vegetation, sagebrush.  
Timber, none.

From the cor. of secs. 13, 18, 19 and 24 on E. bdy of the Tp., which is an iron post, 2 ins. diam., properly set, marked and witnessed as described in the field notes of the resurvey of the West Boundary of T. 15 N., R. 94 W.

S.  $89^{\circ} 54'$  W., on true line, bet. secs. 13 and 24.

Over broken desert, through scattered sagebrush and greasewood.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

## Chains.

1.99	Dry wash, course S.
11.96	Dry wash, course S.
40.05 $\frac{1}{2}$	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 12 ins. in ground to underlying rock and in a mound of stone to top for the restored 1 sec. cor., with brass cap mkd.
	$\frac{1}{4}$ S13 S24 1938
49.23	Dry wash, course S. 30° W.
80.11	The cor. of secs. 13, 14, 23 and 24.  Land, rolling and broken desert. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	N. 0° 25' E., on true line bet. secs. 13 and 14.  Over rolling desert, through scattering sagebrush and greasewood.
4.24	Dry drain, course SW.
40.11	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 8 ins. in the ground to underlying rock and in a mound of stone to top, for the restored 1 sec. cor., with brass cap mkd.
	S14 S13 1938
80.22	At proportionate distance.  Set an iron post, 3 ft. long, 2 ins. diam., 4 ins. in ground to underlying rock and in a mound of stone to top, for the restored cor. of secs. 11, 12, 13 and 14, with brass cap mkd.
	T15N R95W S11 S12 S14 S13 1938
	Land, rolling and broken desert. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	From the cor. of sec. 7, 12, 13 and 18, on the E. bdy. of the Tp., which is an iron post, 2 ins. diam., properly set, marked and witnessed as described in the field notes

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Cheins.	of the resurvey of the West Boundary of T. 15 N., R. 94 W. S. $89^{\circ} 53'$ W., on true line, bet. secs. 12 and 13. Over rolling to broken desert, through scattered sagebrush and greasewood.
18.06	Dry wash, course SW.
25.35	Dry wash, course SW.
39.97	At proportionate point. Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored 1 sec. cor., with brass cap mkd.
	$\frac{S12}{S13}$ 1938
	dig pits 18 x 18 x 12 ins., E. and W. of post, 3 ft. dist.
79.94	The cor. of secs. 11, 12, 13 and 14. Land, rolling to broken desert. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	N. $0^{\circ} 06'$ E., on true line, bet. secs. 11 and 12. Over rolling to broken desert, through scattered sagebrush and greasewood.
18.30	Dry wash, course S. $70^{\circ}$ W.
40.11	At proportionate distance. Set an iron post, 3 ft. long, 1 in. diam., 6 ins. in ground to underlying rock and in a mound of stone to top, for the restored 1 sec. cor., with brass cap mkd.
	$\frac{S11}{S12}$ 1938
80.22	At proportionate point. Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for the restored cor. of secs. 1, 2, 11 and 12, with brass cap mkd.
	T15N R95W $\frac{S2}{S1}$ $\frac{S11}{S12}$ 1938

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

	Chains.	Land, rolling to broken desert. Soil, sandy clay and rocky; 3d rate. Vegetation, scattered sagebrush and greasewood. Timber, none..
		From the cor. of secs. 1, 6, 7 and 12, on the E. bdy. of the Tp., which is an iron post, 2 ins. diam., properly set, marked and witnessed as described in the field notes of the resurvey of the W. bdy. of T. 15 N., R. 94 W.
		S. 89° 55' W., on true line, bet. secs. 1 and 12.
		Over rolling desert, through scattered sagebrush and greasewood.
40.03		At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 18 ins. in the ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{2}$ sec. cor., with brass cap mkd.
		$\frac{1}{2} \frac{S1}{S12}$ 1938
80.06		The cor. of secs. 1, 2, 11 and 12.  Land, rolling desert. Soil, sandy clay and rocky. Vegetation, scattered sagebrush and greasewood. Timber, none.
		N. 0° 29' E., on true line, bet. secs. 1 and 2.  Over broken desert, through scattered sagebrush and greasewood.
26.35		Dry wash, course S. 70° W.
40.11		At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 6 ins. in ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{2}$ sec. cor., with brass cap mkd.
		$\frac{1}{2}$ S2 S1 1938
48.29		Dry wash, course S. 70° W.
65.31		Dry wash, course S. 70° W.
76.27		Ridge, bears NE. and SW.
80.42		The cor. of secs. 1, 2, 35 and 36, on N. bdy. of the Tp., which is an iron post, 2 ins. diam., properly set, mkd. and witnessed as described in the field notes of the resurvey of the S. Bdy. of T. 16 N., R. 95 W.

## Dependent Survey of the Subdivision of T. 15 N., R. 95 W.

Chains.

Land, broken desert.  
 Soil, sandy clay and rocky; 3d rate.  
 Vegetation, sagebrush and greasewood.  
 Timber, none.

From the cor. of secs. 2, 3, 34 and 35, on the S. bdv. of the Tp., hereinbefore described.

N.  $0^{\circ} 21'$  E., on true line, bet. secs. 34 and 35.

Over broken desert, through scattered sagebrush and greasewood..

0.90 Dry wash, course N.  $60^{\circ}$  E.

22.31 Dry wash, course N.  $70^{\circ}$  E.

32.91 Right bank of Sand Creek, dry, course S.  $40^{\circ}$  E.

35.81 Left bank of Sand Creek.

40.11 Proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 4 ins. in ground to underlying rock and in a mound of stone to top, for the restored  $\frac{1}{2}$  sec. cor., with brass cap mkd.

4

S34|S35

1938

47.50 Low spur; slopes W.

49.60 Left bank of Sand Creek, dry, course S.  $40^{\circ}$  W.; thence across nearly level bed of Sand Creek.

57.08 Right bank of Sand Creek.

70.08 Right bank of Sand Creek, dry; course S.  $40^{\circ}$  E.

72.77 Left bank of Sand Creek; leave bottom land of Sand Creek.

80.22 At proportionate point.

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in ground, for the restored cor. of secs. 26, 27, 34 and 35, with brass cap mkd.

T15N R95W

S27|S26

S34|S35

1938

raise a mound of stone,  $3\frac{1}{2}$  ft. base, 2 ft. high W. of post.

Land, broken desert.  
 Soil, stony clay and rocky; 3d rate.  
 Vegetation, sagebrush and greasewood.  
 Timber, none.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.	From the cor. of secs. 25, 26, 35 and 36, hereinbefore described. N. 89° 53' W., on true line, bet. secs. 26 and 35. Over rolling prairie, through scattered sagebrush and greasewood.
5.87	Dry wash, course S. 70° W.
35.27	Dry wash, course S. 70° E., heads 1 ch. NW.
39.88	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in ground, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ S26 ✓ S35 1938
64.62	dig pits, 18 x 18 x 12 ins., E. and W. of post, 3 ft. dist. Dry wash, course S. 60° W.
79.77	The cor. of secs. 26, 27, 34 and 35.  Land, rolling prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	N. 0° 02' E., on true line, bet. secs. 26 and 27.  Over rolling prairie, through scattered sagebrush and greasewood.
40.11	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	S27   S26 ✓ 1938
58.11	dig pits, 18 x 18 x 12 ins., N. and S. of post, 3 ft. dist.
80.22	Main drain, dry, course S. 60° W.  At proportionate point.  Set an iron post, 3 ft. long, 2 ins. diam., 8 ins. in ground to underlying rock, and in a mound of stone to top, for the restored cor. of secs. 22, 23, 26 and 27, with brass cap mkd.
	T15N R95W S22   S23 ✓ S27   S26 1938

## Dependent Resurvey of the Subdivisions of T. 15 N., R. 95 W.

Chains.

Land, rolling semi desert.  
 Soil, sandy clay and rocky; 3d rate.  
 Vegetation, sagebrush and greasewood.  
 Timber, none.

From the cor. of secs. 23, 24, 25 and 26, hereinbefore described.

N.  $89^{\circ} 53'$  W., on true line, bet. secs. 23 and 26

Over rolling desert, through scattered sagebrush and greasewood.

1.44 Dry drain, course S.  $30^{\circ}$  W.

3.94 Same drain, course N.  $60^{\circ}$  W.

14.34 Same drain, course S.  $60^{\circ}$  W.

17.04 Short dry wash, course S.  $60^{\circ}$  W.

25.74 Same drain as at 14.34, course N.  $70^{\circ}$  W.

33.04 Same drain, course S.  $60^{\circ}$  W.

39.84 At proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored  $\frac{1}{4}$  sec. cor., with brass cap mkd.

4 S23  
S26  
1938

raise a mound of stone,  $2\frac{1}{2}$  ft. base,  $2\frac{1}{2}$  ft. high N. of cor.

45.64 Same drain, at head, course SW. from SE.

53.54 Same drain, course N.  $85^{\circ}$  W.

62.54 Same drain, course S.  $60^{\circ}$  W.

79.68 The cor. of secs. 22, 23, 26 and 27.

Land, rolling prairie.  
 Soil, sandy clay and rocky; 3d rate.  
 Vegetation, sagebrush and greasewood.  
 Timber, none.

N.  $0^{\circ} 01'$  W., on true line, bet. secs. 22 and 23.

Over rolling desert, through scattered sagebrush and greasewood.

40.11 At proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 14 ins. in ground to underlying rock and in a mound of stone to top, for the restored  $\frac{1}{4}$  sec. cor., with brass cap mkd.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

	Chains.	$\frac{1}{4}$ S22 S23 1938
54.75	Dry wash, course S. 50° W.	
80.22	At proportionate point.  Set an iron post, 3 ft. long 2 ins. diam., 12 ins. in ground to underlying rock and in a mound of stone to top for the restored cor. of secs. 14, 15, 22 and 23, with brass cap md.	T15N R95W S15 S14 S22 S23 1938
	Land, rolling prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.	
	From the cor. of secs. 13, 14, 23 and 24, hereinbefore described.	
	N. 89° 53' W., on true line, bet. secs. 14 and 23.	
	Over rolling prairie land, through scattered sagebrush and greasewood.	
3.80	Dry drain, course S. 30° W.	
40.01	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 8 ins. in the ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{4}$ sec. cor., with brass cap md.	$\frac{1}{4}$ — S14 S23 1938
41.58	Dry wash, course SW.	
64.97	Dry wash, course SW.	
80.03	The cor. of secs. 14, 15, 22 and 23.  Land, rolling prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.	
	N. 0° 38' E., on true line, bet. secs. 14 and 15.  Over rolling to broken prairie, through sagebrush and greasewood.	
38.25	Dry wash, course generally W.	

Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.	
40.11	At proportionate point. Set an iron post, 3 ft. long, 1 in. diam., 8 ins. in the ground and in a mound of stone to top, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.  $\frac{1}{4}$ S15   S14 ✓ 1938
47.11	Dry wash, course S. $70^{\circ}$ W.
80.22	At proportionate point. Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in ground, for the restored cor. of secs. 10, 11, 14 and 15, with brass cap mkd.  T15N R95W S10   S11 S15   S14 1938  raise a mound of stone, 3 ft. base, $2\frac{1}{2}$ ft. high W. of cor. From this cor. a prominent knoll, 10 chs. diam., bears N. $60^{\circ}$ E., 20.00 chs. dist. Land, broken prairie. Soil, sandy clay and rocky. Vegetation, sagebrush and greasewood. Timber, none.
27.63	From the cor. of secs. 11, 12, 13 and 14, hereinbefore described: N. $89^{\circ} 55'$ W., on true line, bet. secs. 11 and 14. Over broken prairie land, through sagebrush and gresso- wood.
39.87	Dry wash, course S. $50^{\circ}$ W. At proportionate point. Set an iron post, 3 ft. long, 1 in. diam., 18 ins. in ground to underlying rock and in a mound of stone to top for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.  S11 $\frac{1}{4}$ — S14 1938.
44.74	Dry wash, course S.
79.74	The cor. of secs. 10, 11, 14 and 15. Land, rolling and broken prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.

## Dependent Survey of the Subdivision of T. 15 N., R. 95 W.

	N. 0° 04' W., on true line, bet. secs. 10 and 11. Over broken prairie land, through scattered sagebrush and greasewood.
2.84	Knoll, on line, 2 chs. diam.
13.63	Dry wash, course generally W.; heads about 8 chs. E.
21.80	Dry wash, course N. 70° W.; heads about 20 chs. E.
40.11	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 4 ins. in the ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ S10 S11 1938
43.21	Dry wash, course S. 60° W., heads about 25 chs. E.
78.79	Dry wash, course S. 60° W., heads about 20 chs. E.
80.22	At proportionate point.  Set an iron post, 3 ft. long, 2 ins. diam., 4 ins. in ground to underlying rock and in a mound of stone to top, for the restored cor of secs. 2, 3, 10 and 11, with brass cap mkd.
	T15N R95W S3 S2 S10 S11 1938
	Land, broken prairie. Soil, sandy clay and loam; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	From the cor. of secs. 1, 2, 11 and 12, hereinbefore described.
	N. 80° 55' W., on true line bet. secs. 2 and 11. Over rolling prairie land, through scattered sagebrush and greasewood.
24.58	Dry wash, course S. 30° E.
39.95 $\frac{1}{2}$	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 20 ins. in the ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ S2 S11 1938
79.91	The cor. of secs. 2, 3, 10 and 11.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.	Land, rolling and broken prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	N. 0° 29' E., on true line, bet. secs. 2 and 3.
	Over broken prairie land, through scattered sagebrush and greasewood.
40.11	At proportionate point.
	Set an iron post, 3 ft. long, 1 in. diam., 16 ins. in ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{2}$ sec. cor., with brass cap mkd.
	$\frac{1}{2}$
	S3 S2
	1938
57.00	Dry wash, course generally W.
76.51	Dry wash, course S. 70° W.
80.33	The cor. of secs. 2, 3, 34 and 35, on N. bdy. of the Tp., which is an iron post, 2 ins. diam., properly set, mkd. and witnessed as described in the field notes of the resurvey of the S. Bdy. of T. 16 N., R. 95 W.
	Land, broken prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	From the cor. of secs. 3, 4, 33 and 34, on the S. bdy. of the Tp., hereinbefore described
	N. 0° 05' W., on true line, bet. secs. 33 and 34.
	Over broken prairie land, through scattered sagebrush and greasewood.
25.98	Knoll, on line, 2 chs. diam.
40.13	At proportionate point.
	Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored $\frac{1}{2}$ sec. cor., with brass cap mkd.
	$\frac{1}{2}$
	S33 S34
	1938
	raise a mound of stone, 2 ft. base, 2 ft. high, W. of cor.
44.64	Dry wash, course S. 70° E.
56.12	Dry wash, course S. 70° E.; heads about 5 chs. W.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.	
59.11	Knoll, 2 chs. diam., on line.
80.26	At proportionate point.  Set an iron post, 3 ft. long, 2 ins. diam., 8 ins. in the ground to underlying rock and in a mound of stone to top, for the restored cor. of secs. 27, 28, 33 and 34, with brass cap mkd.
	T15N R95W S28   S27 --- S33   S34 1938
	Land, broken prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	From the cor. of secs. 26, 27, 34 and 35, hereinbefore described.
	N. 89° 55' W., on true line, bet. secs. 27 and 34.
	Over broken prairie land, through sagebrush and greasewood.
7.58	Left bank of Sand Creek, dry, course S. 30° E.
12.98	Right bank of Sand Creek.
31.77	Dry drain, course N. 30° W.
40.15	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored $\frac{1}{2}$ sec. cor., with brass cap mkd.
	S27 ✓ --- S34 1938
	raise a mound of stone, 2 $\frac{1}{2}$ ft. base, 2 ft. high, N. of cor.
41.60	Dry drain, course N. 60° E.
67.48	Dry drain, course N.; heads 1 ch. S. of line.
80.31	The cor. of secs. 27, 28, 33 and 34.  Land, broken prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	From the cor. of secs. 26, 27, 34 and 35, hereinbefore described.
	N. 0° 19' E., on true line, bet. secs. 27 and 28.
	Over rolling to broken prairie land, through sagebrush and greasewood.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.	
18.52	Dry wash, course S. 60° E.
40.13	At proportionate point. Set an iron post, 3 ft. long, 1 in. diam., 12 ins. in the ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$
	S28   S27 ✓
	1938
51.94	Low spur, slopes E.
76.66	Low spur, slopes E.
80.26	At proportionate point. Set an iron post, 3 ft. long, 2 ins. diam., 10 ins. in the ground to underlying rock and in a mound of stone to top, for the restored cor. of secs. 21, 22, 27 and 28, with brass cap mkd.
	T15N R95W S21   S22 S28   S27 1938
	Land, rolling and broken prairie. Soil, sandy clay and loam; 2d and 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
39.96½	From the cor. of secs. 22, 23, 26 and 27, hereinbefore described. N. 89° 51' W., on true line, bet. secs. 22 and 27. Over rolling prairie land, through sagebrush and greasewood. At proportionate point. Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ ————— S22 . ✓ S27 1938
	dig pits 18 x 18 x 12 ins., E. and W. of post, 3 ft. dist.
49.56	Dry drain, course S. 20° E.
70.03	The cor. of secs. 21, 22, 27 and 28. Land, rolling prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

	Chains.	N. $0^{\circ} 12'$ W., on true line, bet. secs. 21 and 22. Over rolling prairie, through sagebrush and greasewood.
37.80	Dry drain, course S. $40^{\circ}$ E.	
40.13	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.	$\frac{1}{4}$ S21 S22 1938
		raise a mound of stone, $2\frac{1}{2}$ ft. base, 2 ft. high, W. of post.
49.83	Dry drain, course S. $30^{\circ}$ W.	
80.26	At proportionate point.  Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in ground, for the restored cor. of secs. 15, 16, 21 and 22, with brass cap mkd.	T15N R95W S16 S15 S21 S22 1938
		raise a mound of stone, $2\frac{1}{2}$ ft. base, 2 ft. high, W. of cor.
	Land, rolling prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.	
	From the cor. of secs. 14, 15, 22 and 23, hereinbefore described. N. $89^{\circ} 47'$ W., on true line, bet. secs. 15 and 22.	
	Over rolling prairie, through sagebrush and greasewood.	
2.36	Small dry drain, course S. $30^{\circ}$ W.	
40.051	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.	$\frac{1}{4}$ S15 S22 1938
		raise a mound of stone, 2 ft. base, 2 ft. high, N. of cor.
55.00	Dry wash, course S. $60^{\circ}$ W.	
80.11	The cor. of secs. 15, 16, 21 and 22.	

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.

Land, rolling prairie.  
 Soil, sandy clay and rocky; 3d rate.  
 Vegetation, sagebrush and greasewood.  
 Timber, none.

---

N.  $0^{\circ} 30'$  E., on true line, bet. secs. 15 and 16.

Over broken desert, through scattered sagebrush and greasewood.

27.31 Dry drain, course SW.

28.00 Same drain, course SE.

38.30 Same drain, course SW.

40.13 At proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored  $\frac{1}{4}$  sec. cor., with brass cap mkd.

↓  
S16|S15

1938

dig pits

18 x 18 x 12 ins., N. and S. of post, 3 ft. dist.

41.95 Same drain, course SE.

47.75 Same drain, course SW.

80.26 At proportionate point.

Set an iron post, 3 ft. long, 2 ins. diam., 6 ins. in the ground to underlying rock and in a mound of stone to top, for the restored cor. of secs. 9, 10, 15 and 16, with brass cap mkd.

T15N R95W  
S9|S10

S16|S15  
1938

Land, broken prairie.

Soil, sandy clay and rocky; 3d rate.

Vegetation, sagebrush and greasewood.

Timber, none.

---

From the cor. of secs. 10, 11, 14 and 15, hereinbefore described.

N.  $89^{\circ} 47'$  W., on true line, bet. secs. 10 and 15.

Over rolling to broken prairie land, through sagebrush and greasewood.

8.23 Dry drain, course S.  $70^{\circ}$  W.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.	
17.63	Dry wash, course S. $70^{\circ}$ W.
28.59	Dry wash, course N. $30^{\circ}$ W.
40.14	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ S10 S15 1938
	raise a mound of stone, 3 ft. base, $2\frac{1}{2}$ ft. high N. of cor.
58.94	Dry drain, course S. $60^{\circ}$ W.
80.28	The cor. of secs. 9, 10, 15 and 16.  Land, rolling and broken. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	N. $0^{\circ} 21'$ E., on true line, bet. secs. 9 and 10.  Over broken prairie land, through scattered sagebrush and greasewood.
40.13	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 18 ins. in the ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ S9 S10: 1938
42.36	Dry drain, course S. $60^{\circ}$ W.
57.22	Dry drain, course generally W.
61.32	Dry drain, course generally W.
74.87	Dry drain, course S. $40^{\circ}$ W.
80.26	At proportionate point.  Set an iron post, 3 ft. long, 2 ins. diam., 6 ins. in ground to underlying rock and in a mound of stone to top, for the restored cor. of secs. 3, 4, 9 and 10, with brass cap mkd.
	T15N R05W S4 S3 S9 S10 1938

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.

Land, broken prairie.  
 Soil, sandy clay and rocky; 3d rate.  
 Vegetation, scattered sagebrush and greasewood.  
 Timber, none.

---

From the cor. of secs. 2, 3, 10 and 11, hereinbefore described.

N. 89° 44' W., on true line, bet. secs. 3 and 10.

Over gently rolling land, through scattered sagebrush and greasewood.

39.91

At proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 9 ins. in ground to underlying rock and in a mound of stone to top, for the restored  $\frac{1}{4}$  sec. cor., with brass cap mkd.

$\frac{1}{4}$  S3 ✓  
S10  
1938

62.64

Dry wash, course S. 40° W.

79.82

The cor. of secs. 3, 4, 9 and 10.

Land, rolling.

Soil, sandy clay and rocky; 3d rate.  
 Vegetation, sagebrush and greasewood.  
 Timber, none.

---

N. 0° 31' E., on true line, bet. secs. 3 and 4.

Over rolling land, through scattered sagebrush and greasewood.

23.00

Dry drain, course S. 40° W.

40.13

At proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored  $\frac{1}{4}$  sec. cor., with brass cap mkd.

$\frac{1}{4}$   
S4|S3 ✓  
1938

raise a mound of stone, 3 $\frac{1}{2}$  ft. base, 2 ft. high, W. of cor.

79.98

The cor. of secs. 3, 4, 33 and 34, on N. bdy. of the Tp., which is an iron post, 2 ins. diam., properly set, mkd. and witnessed as described in the field notes of the resurvey of the S. Bdy. of T. 16 N., R. 95 W.

Land, rolling prairie.

Soil, sandy clay and rocky.

Vegetation, sagebrush and greasewood.

Timber, none.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

	Chains.	From the cor. of secs. 4, 5, 32 and 33, on the S. bdy. of the Tp., hereinbefore described.
		N. 0° 02' E., on true line, bet. secs. 32 and 33.
		Over nearly level prairie, through sagebrush and greasewood.
40.14	At proportionate point.	Set an iron post, 3 ft. long, 1 in. diam., 16 ins. in the ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
		S32   S33 1938
		Continue over level prairie.
80.29	At proportionate point.	Set an iron post, 3 ft. long, 2 ins. diam., 20 ins. in the ground to underlying rock and in a mound of stone to top for the restored cor. of secs. 28, 29, 32 and 33, with brass cap mkd.
		T15N R95W S29   S28 S32   S33 1938
		Land, nearly level prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
		From the cor. of secs. 27, 28, 33 and 34, hereinbefore described.
		N. 89° 53' W., on true line, bet. secs. 28 and 33.
		Over broken prairie land, through scattered sagebrush and greasewood.
39.88	At proportionate point.	Set an iron post, 3 ft. long, 1 in. diam., 18 ins. in the ground, to underlying rock and in a mound of stone to top for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
		S28 S33 1938
46.09	Crest of escarpment, bears NE. and SE., faces generally E.; thence over nearly level mesa.	
79.77	The cor. of secs. 28, 29, 32 and 33.	Land, broken prairie E. of escarpment, nearly level mesa W. of escarpment. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.	N. $0^{\circ} 03'$ E., on true line, bet. secs. 28 and 29 Over nearly level mesa, through sagebrush and greasewood.
40.14	At proportionate point. Set an iron post, 3 ft. long, 1 in. diam., 18 ins. in ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ S29   S28
	1938
80.29	At proportionate point. Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for the restored cor. of secs. 20, 21, 28 and 29, with brass cap mkd.
	T15N R95W S20   S21 S29   S28 1938
	raise a mound of stone, $2\frac{1}{2}$ ft. base, $2\frac{1}{2}$ ft. high, W. of cor.
	Land, nearly level mesa. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	From the cor. of secs. 21, 22, 27 and 28, hereinbefore described.
	N. $0^{\circ} 51'$ W., on true line, bet. secs. 21 and 28.
	Over broken prairie land, through scattered sagebrush and greasewood.
24.98	Crest of escarpment, bears S. $10^{\circ}$ W and N. $40^{\circ}$ W., faces generally E.; thence over nearly level mesa.
40.08	At proportionate point.
	Set an iron post, 3 ft. long, 1 in. diam., 6 ins. in the ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ S21 S28 1938
80.16	The cor. of secs. 20, 21, 28 and 29. Land, rolling to broken prairie E. of escarpment, nearly level mesa W. of escarpment. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

	Chains.	N. 0° 02' W., on true line, bet. secs. 20 and 21. Over nearly level mesa, through scattered sagebrush and greasewood.
21.23		Small dry wash, course NE., heads about 10 chs. SW.
37.14		Crest of escarpment, bears W. and SE., faces generally N. and NE.; thence over broken prairie.
40.14½		At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground for the restored ¼ sec. cor., with brass cap mkd.
		$\frac{1}{4}$ S20 S21✓
		1938
		raise a mound of stone, 3 ft. base, 2½ ft. high, W. of cor. Continue over broken prairie.
80.29		At proportionate point.  Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in ground, for the restored cor. of secs. 16, 17, 20 and 21, with brass cap mkd.
		T15N R95W S17 S16 S20 S21 1938
		raise a mound of stone, 2½ ft. base, 2 ft. high, W. of cor. Land, nearly level mesa S. of escarpment, rolling to broken prairie, N. of escarpment. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
		From the cor. of secs. 15, 16, 20 and 21. N. 89° 49' W., on true line, bet. secs. 16 and 21. Over rolling prairie land, through sagebrush and greasewood.
6.44		Dry drain, course S., 30° W.
37.14		Dry drain, course generally S.
30.96½		At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored ¼ sec. cor., with brass cap mkd.
		S16 S21 1938

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains. raise a mound  
 of stone,  $2\frac{1}{2}$  ft. base,  $2\frac{1}{2}$  ft. high, N. of cor.  
 44.28 Prominent knoll, bears N., 10 chs. dist.  
 59.28 Small drain, dry, course N.  $60^{\circ}$  E.  
 79.93 The cor. of secs. 16, 17, 20 and 21.  
 Land, rolling prairie.  
 Soil, sandy clay and rocky; 3d rate.  
 Vegetation, sagebrush and greasewood.  
 Timber, none.

N.  $0^{\circ} 24'$  E., on true line, bet. secs. 16 and 17.  
 Over rolling prairie land, through sagebrush and grease-  
 wood.  
 4.90 Prominent knoll bears W., about 6 chs. dist.  
 40.14 $\frac{1}{2}$  At proportionate point.  
 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in  
 the ground, for the restored  $\frac{1}{4}$  sec. cor., with brass  
 cap mkd.

1  
 S17|S16

1938

dig pits  
 18 x 18 x 12 ins., N. and S. of post, 3 ft. dist.

71.51 Escarpment, bears generally E. and W., faces S.; thence  
 over nearly level mesa.  
 80.29 At proportionate point.

Set an iron post, 3 ft. long, 2 ins. diam., 18 ins. in  
 the ground to underlying rock and in a mound of stone  
 to top, for the restored cor. of secs. 8, 9, 16 and 17,  
 with brass cap mkd.

T15N R95W  
 S8|S9  
 S17|S16  
 1938

Land, rolling prairie.  
 Soil, sandy clay and rocky; 3d rate.  
 Vegetation, sagebrush and greasewood.  
 Timber, none.

From the cor. of secs. 9, 10, 15 and 16, hereinbefore  
 described.

N.  $80^{\circ} 46'$  W., on true line, bet. secs. 9 and 16.  
 Over rolling prairie land, through sagebrush and grease-  
 wood.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Cheins.	
22.40	Dim sheep wagon road, bears N. and S.
36.41	Dry drain, course generally S.
40.08½	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 20 ins. in the ground to underlying rock and in a mound of stone to top, for the restored ½ sec. cor., with brass cap mkd.
	1 — <u>SO</u> S16 1938
71.81	Crest of escarpment, bears N. and S., faces E.; thence over rolling mesa.
80.17	The cor. of secs. 8, 9, 16 and 17.  Land, rolling prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	N. 0° 31' E., on true line, bet. secs. 8 and 9.  Over rolling mesa through scattered sagebrush and greasewood.
40.14½	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored ½ sec. cor., with brass cap mkd.
	S8 S9 1938
	raise a mound of stone, 2 ft. base, 2 ft. high W. of post.
54.90	Crest of escarpment, bears NW. and SE., faces NE.; thence over rolling prairie land.
80.29	At proportionate point.  Set an iron post, 3 ft. long, 2 ins. diam., 6 ins. in ground to underlying rock and in a mound of stone to top, for the restored cor. of secs. 4, 5, 8 and 9, with brass cap mkd.
	T15N R95W S5 S4 S8 S9 1938
	Land, rolling prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.	From the cor. of secs. 3, 4, 9 and 10, hereinbefore described. N. $89^{\circ} 43'$ W., on true line, bet secs. 4 and 9. Over rolling prairie land, through sagebrush and greasewood.
9.26	Dry drain, course S. $20^{\circ}$ E.
19.76	Dim sheep wagon road, bears generally N. and S.
33.35	Dry wash, course S. $30^{\circ}$ E.
37.55	Dry wash, course S. $80^{\circ}$ E.
40.01½	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 16 ins. in the ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{2}$ sec. cor., with brass cap mkd.
	$\frac{1}{2}$ S4 S9 1938
42.55	Dim sheep wagon road, bears N. $40^{\circ}$ W. and S. $50^{\circ}$ E.
60.25	Dry wash, course SE.
80.03	The cor. of secs. 4, 5, 8 and 9.  Land, rolling prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	N. $0^{\circ} 48'$ E., on true line, bet. secs. 4 and 5.  Over rolling prairie land, through sagebrush and greasewood.
7.37	Small knoll, on line.
26.30	Dim sheep wagon road, bears NW. and SE.
40.15	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored $\frac{1}{2}$ sec. cor., with brass cap mkd.
	$\frac{1}{2}$ S5 S4 1938
78.81	dig pits, 18 x 18 x 12 ins., N. and S. of post, 3 ft. dist. Dry wash, course E.
79.69	The cor. of secs. 4, 5, 32 and 33, on N. bdy. of the Tp., which is an iron post, 2 ins. diam., properly set, mkd. and witnessed as described in the field notes of the resurvey of the S. bdy. of T. 16 N., R. 95 W.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.

Land, rolling prairie.  
 Soil, sandy clay and rocky; 3d rate.  
 Vegetation, sagebrush and greasewood.  
 Timber, none.

From the cor. of secs. 5, 6, 31 and 32, on the S. bdy. of the Tp., hereinbefore described.

N. 0° 02' W., on true line, bet. secs. 31 and 32.

Over rolling prairie land, through sagebrush and greasewood.

15.00 Dry wash, course generally W.

27.82 Dry wash, course S. 60° W.

40.14 At proportionate distance.

Set an iron post 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored  $\frac{1}{2}$  sec. cor., with brass cap mkd.

<sup>1</sup>  
S31|S32

1938.

18 x 18 x 12 ins., N. and S. of post, 3 ft. dist. dig pits,

54.55 Dry drain, course generally S. 50° W.

80.28 At proportionate point.

Set an iron post, 3 ft. long, 2 ins. diam., 18 ins. in the ground to underlying rock and in a mound of stone to top, for the restored cor. of secs. 29, 30, 31 and 32, with brass cap mkd.

T15N R95W  
S30|S20  
S31|S32  
1938

Land, rolling prairie.  
 Soil, rocky, sandy clay; 3d rate.  
 Vegetation, sagebrush and greasewood.  
 Timber, none.

From the cor. of secs. 28, 29, 32 and 33, hereinbefore described.

N. 89° 53' W., on true line, bet. secs. 29 and 32.

Over rolling prairie land, through sagebrush and greasewood.

20.90 Dry drain, course S. 60° W.

39.96 At proportionate point.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 05 W.

Chains.	Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ ————— S29 S32 1938
79.03	18 x 18 x 12 ins., E. and W. of post, 3 ft. dist. dig pits, The cor. of secs. 29, 30, 31 and 32. Land, rolling prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
40.00	N. 89° 52' W., on true line, bet. secs. 30 and 31. Over rolling prairie land, through scattered sagebrush and greasewood. At proportionate point. Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ ————— S30 S31 1938
74.62	raise a mound of stone, 2 ft. base, 2 ft. high N. of cor. Small knoll, bears S., about 20 lks.
77.69	The cor. of secs. 25, 30, 31 and 36 on the W. bdy. of the Tr., hereinbefore described. Land, rolling prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
19.70	From the cor. of secs. 29, 30, 31 and 32, hereinbefore described. N. 0° 03' W., on true line, bet. secs. 29 and 30. Over nearly level prairie land, through scattered sagebrush and greasewood.
40.14	Dry drain, course generally W. At proportionate point. Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.	
	$\frac{1}{4}$
80.28	S30   S29 1938
	dig pits 18 x 18 x 12 ins., N. and S. of post, 3 ft. dist.
	At proportionate point.  Set an iron post, 3 ft. long, 2 ins. diam., 8 ins. in ground to underlying rock and in a mound of stone to top, for the restored cor. of secs. 19, 20, 29 and 30, with brass cap mkd.
	T15N R95W S19   S20 S30   S29 1938
	Land, nearly level prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
40.05	  From the cor. of secs. 20, 21, 28 and 29, hereinbefore described.  N. 89° 59' W., on true line, bet. secs. 20 and 29.  Over nearly level prairie land, through scattered sagebrush and greasewood.
66.29	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 8 ins. in ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
80.11	$\frac{1}{4}$ S20 S29 1938
	Dim sheep wagon road, bears generally N. and S.  The cor. of secs. 19, 20, 29 and 30.  Land, nearly level prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
25.78	  N. 89° 55' W., on true line, bet. secs. 19 and 30.  Over nearly level prairie land, through scattered sagebrush and greasewood.
39.98	Dim sheep wagon road, bears N. 40° E. and S. 40° W.  At proportionate point.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored  $\frac{1}{4}$  sec. cor., with brass cap mkd.

$\frac{1}{4}$  S19  
S30  
1938

18 x 18 x 12 ins., E. and W. of post, 3 ft. dist.  
dig pits,

76.98

Dry drain, course S.  $20^{\circ}$  W.

77.08

The cor. of secs. 19, 24, 25 and 30, on the W. bdy. of the Tp., hereinbefore described.

Land, rolling and nearly level prairie.  
Soil, sandy clay and rocky, 3d rate.  
Vegetation, sagebrush and greasewood.  
Timber, none.

From the cor. of secs. 19, 20, 29 and 30, hereinbefore described.

N.  $0^{\circ} 05'$  W., on true line, bet. secs. 19 and 20.

Over nearly level prairie land, through sagebrush and greasewood.

27.60

Dim sheep wagon road, bears N.  $70^{\circ}$  E. and S.  $70^{\circ}$  W.

31.20

Same road, bears N.  $20^{\circ}$  W. and S.  $20^{\circ}$  E.

38.90

Same road, bears N.  $45^{\circ}$  E. and S.  $45^{\circ}$  W.

40.14

At proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored  $\frac{1}{4}$  sec. cor., with brass cap mkd.

 $\frac{1}{4}$ 

S19|S20

1938

raise a mound of stone, 3 ft. base,  $2\frac{1}{2}$  ft. high, W. of cor.

80.28

At proportionate point.

Set an iron post, 3 ft. long, 2 ins. diam., 10 ins. in the ground to underlying rock and in a mound of stone to top, for the restored cor. of secs. 17, 18, 19 and 20, with brass cap mkd.

T15N R95W

S18|S17

S19|S20

1938

Land, rolling prairie.

Soil, sandy clay and rocky; 3d rate.

Vegetation, sagebrush and greasewood.

Timber, none.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.	From the cor. of secs. 16, 17, 20 and 21, hereinbefore described.  N. 89° 55' W., on true line, bet. secs. 17 and 20.  Over rolling prairie land, through scattered sagebrush and greasewood.
40.11	At proportionate point.  Set an iron post, $\frac{3}{4}$ ft. long, 1 in. diam., 16 ins. in the ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ S17 S20 1938
59.57	Crest of escarpment, bears generally N. and S., faces E.; thence over nearly level prairie.
64.07	Dim sheep wagon road, bears S. 10° W., and N. 20° E.
80.22	The cor. of secs. 17, 18, 19 and 20.  Land, rolling prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	N. 89° 58' W., on true line, bet. secs. 18 and 19.  Over rolling prairie land, through scattered sagebrush and greasewood.
30.09	At proportionate point.  Set an iron post, $\frac{3}{4}$ ft. long, 1 in. diam., 27 ins. in the ground, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ S18 S19 1938
	raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, N. of cor.
51.95	Dry drain, course S.
65.05	Dry wash, course S. 20° W.
70.85	Dry wash, course generally S.
76.50	The cor. of secs. 13, 18, 19 and 24, hereinbefore described.  Land, rolling prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

	From the cor. of secs. 17, 18, 19 and 20, hereinbefore described.
	N. 0° 40' E., on true line, bet. secs. 17 and 18.
	Over nearly level prairie land, through scattered sagebrush and greasewood.
40.14½	At proportionate point.
	Set an iron post, 3 ft. long, 1 in. diam., 8 ins. in ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$
	S18 S17 ✓
	1938
80.29	At proportionate point.
	Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in ground, for the restored cor. of secs. 7, 8, 17 and 18, with brass cap mkd.
	T15N R95W S7 S8 / S18 S17
	1938
	raise a mound of stone, $2\frac{1}{2}$ ft. base, $2\frac{1}{2}$ ft. high, W. of cor.
	Land, nearly level prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	From the cor. of secs. 8, 9, 16 and 17, hereinbefore described.
	N. 89° 54' W., on true line, bet. secs. 8 and 17.
	Over nearly level prairie land, through scattered sagebrush and greasewood.
30.64	Dim sheep wagon road, bears generally N and S.
39.95	At proportionate point.
	Set an iron post, 3 ft. long, 1 in. diam., 8 ins. in ground to underlying rock and in a mound of stone to top, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ — S8 S17 1938
79.90	The cor. of secs. 7, 8, 17 and 18.
	Land, nearly level prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.	S. 89° 55' W., on true line, bet. secs. 7 and 18. Over rolling prairie land, through scattered sagebrush and greasewood.
39.99	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ — S7 S18 1938
	dig pits, 18 x 18 x 12 ins., E. and W. of post, 3 ft. dist.
57.28	Ridge, bears generally N. and S.
76.87	The cor. of secs. 7, 12, 13 and 18, on the W. bdy. of the Tr., hereinbefore described.  Land, rolling prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.
	From the cor. of secs. 7, 8, 17 and 18, hereinbefore described.
	N. 0° 45' E., on true line, bet. secs. 7 and 8.
	Over rolling prairie land, through scattered sagebrush and greasewood.
35.94	Dry drain, course S. 65° W.
40.14 $\frac{1}{2}$	At proportionate point.  Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ S7 S8 1938
	dig pits, 18 x 18 x 12 ins., N. and S. of post, 3 ft. dist.
80.29	At proportionate distance.  Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in ground, for the restored cor. of secs. 5, 6, 7 and 8, with brass cap mkd.
	T15N R95W S6 S5 S7 S8 1938
	raise a mound of stone, 2 ft. base, 2 ft. high, W. of cor.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

Chains.

Land, rolling prairie.  
 Soil, sandy clay and rocky; 3d rate..  
 Vegetation, sagebrush and greasewood.  
 Timber, none.

From the cor. of secs. 4, 5, 8 and 9, hereinbefore described.

N. 89° 52' W., on true line, bet. secs. 5 and 8.

Over rolling prairie land, through scattered sagebrush and greasewood.

11.01 Crest of escarpment, bears NW. and SE., faces NE.

39.82½ At proportionate point.

Set on iron post, 3 ft. long, 1 in. diam., 12 ins. in the ground to underlying rock and in a mound of stone to top, for the restored  $\frac{1}{4}$  sec. cor., with brass cap mkd.

$\frac{1}{4}$  — S5  
S8  
1938

52.31 Dim sheep wagon road, bears N. 30° W., and S. 30° E.

79.65 The cor. of secs. 5, 6, 7 and 8.

Land, rolling prairie.  
 Soil, sandy clay and rocky; 3d rate.  
 Vegetation, sagebrush and greasewood.  
 Timber, none.

S. 80° 45' W., on true line, bet. secs. 6 and 7.

Over rolling prairie land, through scattered sagebrush and greasewood.

39.96 At proportionate point.

Set on iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the restored  $\frac{1}{4}$  sec. cor., with brass cap mkd.

$\frac{1}{4}$  — S6  
S7  
1938

dig pits,  
 18 x 18 x 12 ins., E. and W. of post, 3 ft. dist.

62.96 Dim sheep wagon road, bears NE. and SW.

77.36 The cor. of secs. 1, 6, 7 and 12, on the W. bdy. of the Tp., hereinbefore described.

Land, rolling prairie.  
 Soil, sandy clay and rocky; 3d rate.  
 Timber, none.  
 Vegetation, sagebrush and greasewood.

## Dependent Resurvey of the Subdivision of T. 15 N., R. 95 W.

	Chains.	From the cor. of secs. 5, 6, 7 and 8, hereinbefore described.
		N. 0° 40' E., on true line, bet. secs. 5 and 6.
		Over rolling prairie land, through scattered sagebrush and greasewood.
2.25		Dry drain, course S. 70° W.
32.00		Dim sheep wagon road, bears NW. and SE.
40.15		At proportionate point.
		Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for the restored 4 sec. cor., with brass cap mkd.
		$\frac{1}{4}$
		S6 S5
		1938
		raise a mound of stone, 2 ft. base, 2 ft. high, W. of cor.
52.79		Dim sheep wagon road, bears NE. and SW.
60.00		Crest of escarpment, bears NW. and SE., faces NE.
79.78		The cor. of secs. 5, 6, 31 and 32, on N. bdy of the Tp., which is an iron post, 2 ins. diam., properly set, mkd. and witnessed as described in the field notes of the resurvey of the S. Bdy. of T. 16 N., R. 95 W.
		Land, rolling prairie. Soil, sandy clay and rocky; 3d rate. Vegetation, sagebrush and greasewood. Timber, none.

---

General Description

---

The surface of the land in T. 15 N., R. 95 W., is rolling sandy desert cut by numerous washes. The soil is sandy clay and rocky. The entire area is arid in character and the NE. quarter may be called semi bad lands.

No timber is found and the vegetation consists of sagebrush and greasewood.

No habitation is found and the area is used chiefly as a winter range for sheep. The secondary roads are used for bringing supplies to the sheep camps.

No live water is found but Sand Creek, which drains in a southeasterly direction, has water in holes most of the year.

An interesting escarpment traverses the west half of the township.

Interesting fossils are found, but no indication of mineral deposits was noted.



4-680

## **FIELD ASSISTANTS.**

NAMES.	CAPACITY.
Carroll O 'Neill,	Prin. Asst.
Elmer Maki,	2nd Chainman.
John Kovacich,	Axman.
Renaldo Zuech,	Axman.
Chas. Wanner,	Flagman.
Wm. W. Olds,	Cornerman.
Allen R. Bigler,	Flagman.
Geo. Karras,	Flagman.

## CERTIFICATE OF UNITED STATES SURVEYOR

I, Ross W. Moor, Transitman, ~~of the Surveyor~~, hereby certify upon honor that, in pursuance of special instructions received from the District Cadastral Engineer for Wyoming, bearing date of the 21st day of March, 1934, I have well, faithfully, and truly in my own proper person, and in strict conformity with said instructions, the Manual of Surveying Instructions, and the laws of the United States, <sup>retraced</sup> ~~surveyed~~ all those parts or portions of the South and West Boundaries of Township No. 15 North, Range No. 95 West,

of the 6th

Principal Meridian, in the State of Wyoming, which are represented in the foregoing field notes as having been executed by me, and under my direction; and that all the corners of said survey have been established and perpetuated in strict accordance with the Manual of Surveying Instructions, and the special written instructions of the District Cadastral Engineer for Wyoming and in the specific manner described in the field notes, and that the foregoing are the original field notes of such survey.

Dec. 12, 1934  
Savannah, Ga.

*Ross W. Moor*  
Transitman U.S. Surveyor

## APPROVAL

OFFICE OF U. S. SUPERVISOR OF SURVEYS,

, 19

The foregoing field notes of the survey of

executed by

under his special instructions dated                   , 19          , having been critically examined, and the necessary corrections and explanations made, the said field notes, and the surveys they describe, are hereby approved.

*U. S. Supervisor of Surveys.*

I certify that the foregoing transcript of the field notes of the above-described surveys in                   , has been correctly copied from the original notes on file in this office.

*U. S. Supervisor of Surveys.*

**4-680**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GENERAL LAND OFFICE

## FIELD ASSISTANTS

NAMES	CAPACITY
Edward Stevens	Principal Assistant
Ishmael Olsen	Chairman
Robert H. Creswell	Flagman
John Haass	Axeman
Mike Tomich	Cornerman
Dean Warren	Truck driver

## CERTIFICATE OF SURVEYOR

I, Marvin J. Lytle, Cadastral Engineer, HEREBY CERTIFY upon honor that, in pursuance of special instructions bearing date of the 21st day of March, 1934, received from the district cadastral engineer for Wyoming, with assignment instructions dated May 6, 1936, I have surveyed dependently resurveyed the West and South Boundaries of Township No. 15 North, Range No. 95 West.

of the Sixth Principal Meridian, in the State of Wyoming, which are represented in the foregoing field notes as having been executed by me and under my direction; and that said survey has been made in strict conformity with said instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in the specific manner described in the foregoing field notes.

Cheyenne, Wyoming

February 10, 1937

*Marvin J. Lytle*

Cadastral Engineer

## CERTIFICATE OF APPROVAL

OFFICE OF SUPERVISOR OF SURVEYS,

, 19

The foregoing field notes of the survey of .....

executed by .....

under special instructions dated ....., and assignment instructions dated ....., having been critically examined, and the necessary corrections made prior to their certification by the engineer, the said field notes, and the survey therein described, are hereby approved.

*Supervisor of Surveys.*

## CERTIFICATE OF TRANSCRIPT

I CERTIFY that the foregoing transcript of the field notes of the above-described surveys in ....., is a true copy of the original field notes on file in the public survey office.

*Supervisor of Surveys.*

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GENERAL LAND OFFICE

## FIELD ASSISTANTS

NAMES	CAPACITY
Doyle A. Bennett	Principal Assistant
Paul Nicksich	Chairman
Dee Croft	Truck driver
Donald Hull	Cornerman
Parley Burrell	Flagman
Elmer B. Perdue	Cornerman
Lowell Wolfe	Cornerman
Steve O'Mara	Cornerman

## CERTIFICATE OF SURVEYOR

I, Elmer C. Lenhart, Public Land Surveyor, hereby certify upon honor that, in pursuance of special instructions bearing date of the 21st day of March, 1934, received from the district cadastral engineer for Wyoming, with assignment instructions dated April 11, 1938, I have surveyed <sup>re</sup> dependently the subdivisional lines of Township No. 15 North, Range No. 95 West,

of the Sixth Prin. Meridian, in the State of Wyoming, which are represented in the foregoing field notes as having been executed by me and under my direction; and that said survey has been made in strict conformity with said instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in the specific manner described in the foregoing field notes.

Cheyenne, Wyoming

February 2, 1939

Elmer C. Lenhart  
Public Land Surveyor

## CERTIFICATE OF APPROVAL

OFFICE OF SUPERVISOR OF SURVEYS,

Denver, Colorado, June 24, 1941

The foregoing field notes of the survey of dependent resurvey of the south and west boundaries and subdivisional lines of Township No. 15 North, Range No. 95 West, of the Sixth Principal Meridian, in the State of Wyoming,

Ross W. Moor, Transitman; Marvin J. Lytle, Cadastral Engineer; and executed by Elmer C. Lenhart, Public Land Surveyor,

under special instructions dated March 21, 1934, and assignment May 22, 1934; instructions dated May 6, 1936; April 11, 1938, having been critically examined, and the necessary corrections made prior to their certification by the engineer, the said field notes, and the survey therein described, are hereby approved.

Frank M. Johnson  
Supervisor of Surveys.

## CERTIFICATE OF TRANSCRIPT

I CERTIFY that the foregoing transcript of the field notes of the above-described surveys in \_\_\_\_\_, is a true copy of the original field notes on file in the public survey office.

Supervisor of Surveys.